08/17/2010 09:09

8655945753

HEALTH CARE FACILI.

PAGE 21/21 PRINTED: 03/16/2010 FORM APPROVED

STATEMENT OF DEFICIENCIES (XX) PROVIDER/SUPPLIER/OLIA (X2) MULTIFLE CONSTRUCTION (X2) MULTIFLE CONSTRUCTION (X2)	<u>Division</u>	of Health Care Fac	almes		J	· · · · · · · · · · · · · · · · · · ·		ini ma
TINTSOS TOTAL TRANSPORTE OR SUPPUER WHICH HEALTHCARE, MURFREESBORO SUMMANY STATEMENT OF GENCIENCES BY PULL PREPRY TAG I SUMMANY STATEMENT OF GENCIENCES BY PULL PREPRY TAG I SUMMANY STATEMENT OF GENCIENCES BY PULL REGULATORY OR LSG DESTITATION INFORMATION) N 832 1200-8-6-,08(2) Building Standards (2) The condition of the physical plant and the overall nurshing home environment must be developed and maintained in such a manner that the safety and well-being of residents are assured. This Rule is not met as evidenced by: Based on observation it was determined the facility failed to comply with the Tennessee Department of Health building standards. The findings include: Observation of the bookkeeper's office and the speech therapy office on 8/6/10 at 9450 AM, revealed holes in the walls. The mest come by the outpatient therapy area, and the 2nd floor shower room on 8/9/10 at 9350 AM, revealed water stain ceiling tiles. TDOH 1200-8-6-08(2) Observation of Resident room 165 on 8/9/10 at 11:00 AM, revealed the base board under the air conditioner was missing, TDOH 1200-8-8-0.8(2) These findings were acknowledged by the Administrator and verified by the Director of Hadministrator and verified by the Director of Administrator and verified by the Director of Hadministrator and verified by the Director of Hadministrat	STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/OLIA (X1) PROVIDER/SUPPLIER/SUP			A BUILDING 01 - MAIN BUILDING 01		(X3) DATE SURVEY COMPLETED		
NME OF PROVIDER OR SUPPLIER NHC HEALTHCARE, MURFREESBORO SUMMARY STATEMENT OF DEFICIENCIES (20. The Condition of the physical plant and the overall nursing home environment must be developed and maintained in such a manner that the safety and wall-being of residents are assured. This Rule is not met as evidenced by: Based on observation it was determined the facility falled to comply with the Tennessee Department of Health building standards. The findings include: Observation of the Director of Health office, the rest room by the outpatient therapy and to papartment of Health (TDOH) 1200-8-6-08(2) Observation of Resident room 165 on 8/9/10 at 11:00 AM, revealed water stain celling tiles. TDOH 1200-8-6-08(2) Observation of Resident room 165 on 8/9/10 at 11:00 AM, revealed the base board under the air conditioner was missing. TDOH 1200-8-6.08(2) These findings were acknowledged by the Administrator and verified by the Director of Edministrator and verified by the Di		TN7505			B. WING_	B. WING		9/2010
NHC HEALTHCARE, MURFREESBORO AND UNIVERSITY ST SUMMARY STATEMENT OF DEFICIENCIES FREENA TAG SUMMARY STATEMENT OF DEFICIENCY REGULATORY OR LSG IDENTIFYING INFORMATION) N 832 1200-8-6-,08(2) Building Standards (2) The condition of the physical plant and the overall nursing home environment must be developed and maintained in such a manner that the stafety and well-being of residents are assured. This Rule is not met as evidenced by: Based on observation it was determined the facility failed to comply with the Tennessee Department of Health building standards. The findings include: Observation of the bookkeepers office and the speech therapy office and avas repaired on 8/24/10. A door was ordered for the speech therapy office and was repaired on 8/24/10. The ceiling tiles were replaced in the Director of Health Office, the rest room by Outpatient therapy and the 2 nd floor shower room on 8/9/10 at 9:45 AM, revealed motes in the walls. Thenessee, Department of Health (TDOH) 1200-8-6.08(2) Observation of Resident room 165 on 8/9/10 at 1:00 AM, revealed water stain ceiling tiles. TDOH 1200-8-6.08(2) These findings were acknowledged by the Administrator and verified by the Director of facility failings were acknowledged by the Administrator and verified by the Director of	NAME OF B	POVADER OR SUPPLIER		STREET AD	ORESS, CITY,	STATE, ZIP CODE		
PREFIX TAG N 832 1200-8-6-,08(2) Building Standards (2) The condition of the physical plant and the overall nursing home environment must be developed and maintained in such a manner that the safety and well-being of residents are assured. This Rule is not met as evidenced by: Based on observation it was determined the facility failed to comply with the Tennessee Department of Health building standards. The findings include: Observation of the bookkeepers office and the speech therapy office and was repaired on 8/24/10. A door was ordered for the speech therapy office and was repaired on 8/24/10. The ceiling tiles were replaced in the Director of Health Office, the rest room by Outpatient therapy and the 2 nd floor shower room on 8/10 at 9:50 AM, revealed water stain ceiling tiles. TDOH 1200-8-6.08(2) Observation of Resident room 165 on 8/9/10 at 11:00 AM, revealed water stain ceiling tiles. TDOH 1200-8-6.08(2) These findings were acknowledged by the Administrator and verified by the Director of Administration			•	420 M UN MURERES	VERSITY S SBORO, T	N 37130		
(2) The condition of the physical plant and the overall nursing home environment must be developed and maintained in such a manner that the safety and well-being of residents are assured. This Rule is not met as evidenced by: Based on observation it was determined the facility failed to comply with the Tennessee Department of Health building standards. The findings include: Observation of the bookkeepers office and the speech therapy office and was repaired on 8/24/10. A door was ordered for the speech therapy office and was repaired on 8/24/10. The ceiling tiles were replaced in the Director of Health Office, the rest room by the outpatient therapy area, and the 2nd floor shower room on 8/9/10 at 19:50 AM, revealed water stain ceiling tiles. TDOH 1200-8-6.08(2) Observation of Resident room 165 on 8/9/10 at 11:00 AM, revealed the base board under the air conditioner was missing, TDOH 1200-8-6.08(2) These findings were acknowledged by the Administrator and verified by the Director of	PRÉFIX	IFACH DEFICIENCY MUST BE PRECEDED BY FULL			PREFIX (EACH CORRECTIVE ACTION SHO CROSS-REFERENCED TO THE APPR		DUILD BE	
Division of Health Care Facilities (Care Facilities Care Facil		(2) The condition overall nursing ho developed and mithe safety and we assured. This Rule is not represent the safety and we assured. This Rule is not represent of the safety failed to compartment of the speech therapy or revealed holes in Department of the speech therapy or revealed holes in Department of the safety of	of the physical plant me environment mustaintained in such a mil-being of residents and the as evidenced by: atton it was determined and building standard de: a bookkeepers office on 8/9/10 at 9:46 the walls. Tennessed alth (TDOH) 1200-8-be Director of Health operation on 8/9/10 at 9:50 ain ceiling tiles. TDOI desident room 165 on ed the base board unitssing. TDOH 1200-are acknowledged by I verified by the Director of the Director of the Director of Italian at 9:50 ain ceiling tiles. TDOI desident room 165 on ed the base board unitssing. TDOH 1200-are acknowledged by I verified by the Director of the Director of Italian at 9:50 ain ceiling tiles.	anner that are ed the see ds. and the see ds. and the see ds. and the sea, and t	N 832	The Maintenance Director in the bookkeeper's office and resthe holes in the walls. The bookkeeping office was repart to the holes in the walls. The bookkeeping office was repart to the holes in the walls. The bookkeeping office was repart to the property of the property	the vealed ired on if for the is ling tiles of by and floor it on-the air	8/26/10

STATE FORM

LABORATORY DIRECTOR'S OR PROVIDER'S UPPLIER REPRESENTATIVE'S SIGNATURE

FH1321

f continuation attent 1 of "